



**Government of Western Australia  
Department of Transport**

**Notice to Mariners  
Navigational Hazard  
Installation of Cyclone Moorings  
Enderby Island - Dampier**

In addition to *Notice to Mariners: 2011-81*, Mariners are advised that two additional Cyclone Moorings have been installed at Enderby Island, Dampier at the below locations:

**PIL- 00136      Latitude: 20°36.018'S    Longitude: 116°34.344'E**

**PIL- 00137      Latitude: 20°35.877'S    Longitude: 116°34.501'E**

This brings a total of six (6) cyclone moorings in this vicinity.

**Chart AUS 57 (Datum GDA) printed 13 February 2009**

Each Cyclone Mooring is marked with its Mooring registration number and a yellow marker buoy with automatic flashing light, visible to 2nm.

**Mariners are advised to navigate with extreme caution when transiting the area and to navigate well clear of the marker buoys.**

**Raymond Buchholz  
A/Marine Safety Operations Director  
Department of Transport**

**Public Notices – West Australian – 15.12.2011**

**EGN – Pilbara News – 21.12.2011**

Not 2011-162 – Navigational Hazard Installation of Cyclone Moorings,  
Enderby Island, Dampier