

Department of Transport

Port Geographe reconfiguration Previous image galleries

Gallery: Western Beach (monitoring and performance in 2016)



4 December 2015: Less than ~1,000m3 of seagrass wrack




4 December 2015: Less than ~1,000m3 of seagrass wrack



21 April 2016: Less than ~500m3 of seagrass wrack



21 April 2016: Less than ~500m3 of seagrass wrack



9 May 2016




22 May 2016




6 July 2016



9 September 2016



9 September 2016 (Aerial)



15 October 2016




23 November 2016: ~15,000m3 of seagrass wrack



23 November 2016: ~15,000m3 of seagrass wrack (Aerial)


Gallery: Wonnerup Beach (monitoring and performance in 2016)



4 December 2015: After sand nourishment operation in spring 2015



27 May 2016



9 September 2016



23 November 2016: Prior to planned sand nourishment operation in autumn 2017

Gallery: Western Beach (monitoring and performance in 2015)



21 April 2015: Negligible seagrass wrack



21 April 2015: Negligible seagrass wrack



15 June 2015: ~10,000m3 of seagrass wrack



UOVISION

08.07.2015 14:01:20 023 013°C 055°F 009

7 August 2015: Negligible seagrass wrack



24 August 2015: ~6,000m3 of seagrass wrack



24 August 2015: ~6,000m3 of seagrass wrack



29 August 2015: Less than ~500m3 of seagrass wrack



22 September 2015: ~12,500m3 of seagrass wrack



4 December 2015: Less than ~1,000m3 of seagrass wrack



4 December 2015: Less than ~1,000m3 of seagrass wrack

Gallery: Wonnerup Beach (monitoring and performance in 2015)



19 December 2014



21 April 2015



24 August 2015: ~9,000m3 erosion since December 2014



4 December 2015: After ~10,000m3 nourishment operation

Gallery: Changes recorded by aerial photographs (construction works)



July 2013



September 2013



October 2013



December 2013



February 2014



April 2014



June 2014



August 2014



October 2014



December 2014



April 2015